



WHEN 12TEETH PINION GEAR IS USED

motor's mounting screw holes are originally designed to fit 10teeth pinion gear.
Using 12teeth pinion gear will have insufficient movement gap with the adjacent gear.
Hence, the holes have to be enlarged.

